

**IT Aggiornamento alle istruzioni:** codifiche di errori ( 1 ), segnalazioni ( 2 ) e versioni firmware ( 3 ) visualizzati da LK EVO a partire dalla versione firmware 1.2.

**EN Update to the instructions:** error codes ( 1 ), reports ( 2 ), and firmware versions ( 3 ) viewed from LK EVO from firmware version 1.2.

**CZ Aktualizace pokynů :** chybové kódy ( 1 ), hlášení ( 2 ) verze firmware ( 3 ) zobrazení na LK EVO od verze firmware 1.2

**DE Aktualisierungen der Anweisungen:** Fehlercodes ( 1 ), Warnmeldungen ( 2 ) und Firmware-Versionen ( 3 ) ab der Firmware-Version 1.2 von LK EVO angezeigt.

**ES Actualización de las instrucciones:** codificación de los errores ( 1 ), señalizaciones ( 2 ) y versiones del firmware ( 3 ) mostrados por LK EVO a partir de la versión del firmware 1.2.

**NL Bijwerkingen van de instructies:** de codes van fouten ( 1 ), signaleringen ( 2 ) en firmwareversies ( 3 ) die door LK EVO worden weergegeven vanaf de firmwareversie 1.2.

### 1

led 1	led 2	led 3	led 4	led 5	led 6	n°
*						1
		*				4
*		*	*			5
*	*	*				7
	*					9
	*		*			10
*	*		*			11,12,13, 14,20
*	*	*	*			15
				*		16
*	*					17
	*			*		18
*	*			*		19
*		*				21
	*	*		*		22
			*	*		24,31
	*		*	*		26
*	*		*	*		27
*		*	*	*		29
	*	*	*	*		30
			*			32
*				*		38
	*	*	*			39
*	*	*	*	*		99

### 2

led 1	led 2	led 3	led 4	led 5	led 6	n°
*	*					44
*	*				*	51
*	*			*		52
*	*		*			54
*	*		*		*	56
*	*		*	*	*	59
*	*	*				60
*	*	*		*		68

### 3

led 1	led 2	led 3	led 4	led 5	led 6	fw
	*		*			fw 1.0
*	*		*			fw 1.1
		*	*			fw 1.2
*		*	*			fw 1.3



FAAC S.p.A. Soc. Unipersonale  
Via Calari, 10 - 40069 Zola Predosa BOLOGNA - ITALY  
Tel. +39 051 61724 - Fax +39 051 758518  
www.faac.it - www.faacgroup.com